

# 5S Seiketsu - Standardise

The fourth stage in 5S, Standardise;  
conformity in what we do.

# Stages of 5S

- Seiri – Sort (Clearing)
  - clearly separating necessary from unnecessary, and remove unnecessary
- Seiton – Set in order (Configure)
  - visually arrange and identify items for ease of use and retrieval
- Seiso - Shine & Check (Clean & Check)
  - keep the workplace clean (not pretty) to allow problems to be identified
- **Seiketsu - Standardise (Conformity)**
  - **continually monitor the level of clearing, organising and cleaning**
- Shitsuke - Sustain – (Custom & Practice, Consensus)
  - work towards a shared set of values regarding clearing, organising and cleaning
- Safety And the 6<sup>th</sup> S:
  - improve through better clearing, organising, cleaning and visual control

# Why standardize?

- It makes 5S routine.
- Sustains all improvements.
- Builds on the improvements already made.
- Maintains agreed procedures.
- Ensures we don't fall back into our old ways.


# How do we standardize

- Document standard ways of working
  - Standard Operating Procedures (SOP)
- Standardize labeling, signage and flow
- 5S audits

# Standard work


- Document the current agreed way of doing a process.
  - Provides a baseline for improvement
  - Reduces variation between people/shifts

- Use text
- Camera
- video

Gland & Piston Cell - Operator Maintenance					
AREA	M/c SHOP	Machine - TORNAO3	Date	21/06/01	16:15:00
Check Number: 2		Check: Tunnel Squareness and Radial Check			
<b>TUNNEL SQUARENESS</b> 1 Insert test bar into an empty pocket (with no tool) either side. 2 Position test bar so that the X Axis reads 0.000mm on screen. 3 Place DIT on truck so that it touches the end of the test bar. 4 Ensure that the DIT is positioned parallel to the Y Axis and read. 5 Reverse the turret (towards the chuck) and record the dial movement on the DIT. 6 Tolerance of $\pm 0.025mm$ over length of bar allowed. 7 If outside tolerance, perform maintenance as per 2.0.			<b>VISUAL INSPECTIONS</b> 		
<b>Radial Check - (Squareness must be checked first)</b> 1 Place test bar into an empty pocket with no tools inserted side. 2 Remove all tooling data for that pocket from the CMG. 3 Position test bar so that the X Axis reads 0.000mm on screen. 4 Place DIT on truck so that it touches the end of the test bar. 5 Ensure that the DIT is positioned parallel to the Y Axis and read. 6 Rotate the chuck 180 deg. to be opposite the start point and to have dial back end pointing of chipcock. 7 Log the X Axis on incremental mode to move the needle in the opposite direction - until the dial is returned to 0.000. 8 Rotate the chuck back to start point and read DIT to zero. 9 Repeat steps 6 & 7 until the resulting 4 points within tolerance on the DIT. 10 View the DIT in its initial point, note the chuck body and take the deviation. Tolerance of $\pm 0.025mm$ allowed. 11 Any faults found inform maintenance.					
<b>SAFETY INSTRUCTIONS</b> 1 Ensure M/C is stopped. 2 Ensure guards are closed. 3 Wear protective glasses.		<b>EQUIPMENT</b> 1 Test bar 2 Dial Test Indicator 3 Mirror	<b>INSPECTION INSTRUCTIONS</b> 1 Tolerance of 0.025mm allowed on each check. 2 3		

# Standardize flow and signage

- Common methods to show where work enters and leaves a cell.
- Standard methods for identifying components and tool locations
- ✘ 5S is a highly visual tool – everything should be obvious.



# 5S Audit

- Independent audit of an areas adherence to 5S
- Capture current state – use color Photographs
- Create simple audit sheets – With Score

Example checklist:

**Engineering Ltd**  
Workplace Organisation Audit

**Filling Line Seven**

**Pass / Fail**

---

1 (max) pallet of bottles in defined location at scrambler  
1 (max) pallet of collapsed boxes in stacked in defined location  
IBC 1 under mix stand in defined location  
IBC 2 next to IBC 1 in defined location  
1 litter bin in defined location at labeller, not overflowing  
Batch number table surface clear, except magnifying glass  
All handtools on shadowboard at filler  
Head calibration board on peg and filled in and up to date

---

Date:                      Auditor:                      Score:      out of      =      %

- Conduct audits

# 5S auditing

- **Q: Can you write a clear and fair checklist?**
  - those being measured cannot fail or pass for anything ambiguous (eg locations, quantity, cleanliness, etc) - there should be no "shades of grey"**If not, revisit "Organising" to visually clarify groundrules and expectations or rewrite the checklist**
- **Q: Do those being audited agree the audit is fair and reasonable?**
  - have they seen the audit? They can almost certainly devise a better one!
- **Periodically re-audit (eg weekly, fortnightly) and cross-check using auditors from other areas to form auditing group**
- **Give immediate verbal feedback from audit, display results on noticeboard, and chart against past results**
- **Identify problem areas and set targets for improvement**
  - for example, can a lack of cleanliness be prevented through controlling contamination?



# What is the next stage of 5S?

- The hardest step of 5S is that of Shitsuke or Sustaining.
- We need to ensure that we maintain and continuously improve on the gains that we have made through the first 4 steps of 5S

# Copyright and Disclaimer

- Any commercial use of this presentation and the content therein is prohibited without prior permission. Requests for permission to use can be made through the contact page of <http://leanmanufacturingtools.org/contact-page/>
- This presentation is for personal use only and cannot be reproduced or circulated by anyone other than [www.leanmanufacturingtools.org](http://www.leanmanufacturingtools.org)
- Content may be quoted or reproduced for private and educational assignments as long as a proper citation is given referring [leanmanufacturingtools.org](http://leanmanufacturingtools.org)
- The information within this presentation and website are for information purposes only and any action taken is at your own risk.